



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		10		Dodda Bommasandra			
Street ID		Street Name		Significant Landmark			
W0179, W0185, W0152, W0183, W0154		NA		Hanuman Layout and Ramachandrapura			
Segment No.		Total Length (m)					
10/C-W0179/S111125		279.22					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	58.42	77.552361	13.060737	77.552560	13.061228	W0185	W0152
2	61.84	77.552080	13.060792	77.552283	13.061314	W0185	W0152
3	158.96	77.551694	13.060831	77.552816	13.061156	W0065	W0152

Work Details		
History of Road / Lane / Circles		
Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains at Hanuman Layout and Ramachandrapura in ward no 10 Doddabommasandra Vidyanayapura Sub-Division Yelahanka zone	2500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	Roads and Drains
Tender	Work Details	Job No. / Work Code
Tender	Improvements to roads and drains at Hanuman Layout and Ramachandrapura in ward no 10 Doddabommasandra Vidyanayapura Sub-Division Yelahanka zone	010-16-000007
Work Order No.	Work Order Date	Period of Extention
EE/BTP/ BBMP/E- PMT/WO/191/2015-16	03/02/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/01/2017	29/01/2018	Yes

Contractor Details		
Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K SHANKARREDDY		0.00

Zone: YELAHANKA Ward No: 10 Ward Name: Dodda Bommasandra Street ID: W0179, W0185, W0152, W0183, W0154

Phone No.

E-Mail ID

9880650463

Field Inspection Details

Number of Trees

Any Other Information

Name

10

MADHAV RAO

Date of Inspection

Remarks

01/04/2017

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 10

Ward Name: Dodda Bommasandra

Street ID: W0179,
W0185,
W0152,
W0183,
W0154

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks				Remark
Designation	Approver Name	Date	Target Date	
CE	PARAMESHWARAIAH	01/04/2017	03/05/2017	COMPLETED
SE	VASU K M	01/04/2017	03/05/2017	COMPLETED
EE	MOHAN DAS HT	01/04/2017	01/05/2017	COMPLETED
AEE	SHIVAKUMAR	01/04/2017	01/05/2017	COMPLETED
AE	MADHAV RAO	01/04/2017	01/05/2017	COMPLETED
AE	MADHAV RAO	01/04/2017	01/05/2017	COMPLETED

Zone: YELAHANKA

Ward No: 10

Ward Name: Dodda Bommasandra

Street ID: W0179,
W0185,
W0152,
W0183,
W0154